





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

Position



- 2 = A 960 152 NU (4x)
- 3 = A 960 148 NU
- 4 = A 960 150 NU
- 5 = A 960 151 NU
- 7a = A 960 155 NU (2x)
- 10 = A 960 158 NU
- 11 = A 960 161 NU
- 12 = A 960 162 NU
- 13 = A 960 163 NU
- 15 = A 963 544 NU (4x)




PROXIMITY  
A 3794 NU



0208 / A 865 308  
(+ A 865 612)  
Made in Germany



Ideal Standard  
Roentgenstrasse 9  
54516 Wittlich  
Germany





1  
↓  
3



max / min

1

105 max.

G 1/2

G 1/2

80 min.



Batterie erst bei Inbetriebnahme einsetzen.  
Battery only with start-up use.  
Batterie seulement avec l'utilisation de mise en train.  
Inserire la batteria quando introito nell'impresa.

Batterie:  
Battery:  
Pile:  
Batteria:

6V Lithium CR/P2

|  |   |     |  |  |    |
|--|---|-----|--|--|----|
|  | P | bar |  |  |    |
|  | T | °C  |  |  |    |
|  |   |     |  |  | 30 |


2

G 1/2

G 1/2



?



3

MAXIMUM