





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, GN, ...

Pos.	No.
1	A 861 521 XX
2	A 861 417 XX
3	A 861 397 NU
4	A 961 855 NU
5	A 960 019 XX
6	A 963 369 XX
7	A 861 227 XX
8	A 964 520 NU
9	A 962 370 NU
10	A 961 172 NU
11	B 960 900 XX
12	A 961 230 XX




Ideal Standard

CONNECT AIR


A 7030 ..








1120 / A 868 881
Made in Germany



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





P	bar	MAX. 10 0,5	5 1	Q (3 bar)
T	°C	MAX. 85	65 40	l/min 5