





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...






Position

10 = A 961 338 NU
 12 = A 960 401 NU
 14 = A 962 098 XX
 15 = A 961 182 NU (2x)
 16 = A 960 219 NU





Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany



CERAPLUS
A 4167 ..

0208 / A 865 822
 (+ A 865 612)
 Made in Germany





1
↓
2

